## **NOTICE**

## State of South Carolina Department of Health and Environmental Control Columbia, South Carolina

Public Notice #:02493 -01 Date: September 1, 2004

## NOTICE OF PROPOSED CORRECTIVE ACTION

Section 280.67 of the S.C. Underground Storage Tank Control Regulations (R.61-92) requires that any Corrective Action Plan prepared to meet the requirements of 280.66 must be placed on notice for public comment. The following applicant has submitted a Corrective Action Plan for the rehabilitation of groundwater contaminated by petroleum constituents released from underground storage tanks (USTs).

Applicant: PYA Monarch, PO Box 1328, Greenville, SC 29602. PYA Monarch had four petroleum USTs used for storage of petroleum products. Three of the USTs were removed in June 1990 and September 1997. One UST remains in use. The facility is located at 208 Upchurch Road in Walterboro, South Carolina.

## Corrective action will consist of Intrinsic Remediation/Natural Attenuation.

A copy of the file is available for review at the Department's Freedom of Information Office, 2600 Bull Street in Columbia, SC. Please call (803) 898-3880 to schedule an appointment.

Persons wishing to comment upon or object to Corrective Action approval are invited to submit same in writing by October 15, 2004 to South Carolina Department of Health and Environmental Control, Underground Storage Tank Program, 2600 Bull Street, Columbia, S.C. 29201 or call Read Miner at (803) 896-6584. The public notice # should be placed at the top of the first page of comments. Where there is a significant degree of public interest, the Department will hold a public hearing.

Please bring the foregoing to the attention of persons who you know will be interested in this matter.